

Problem 28. Complete the front view. Mark all points of tangency with a short dash. Do not dimension. Use a compass for all circles and arcs. Draw circles and arcs before drawing straight lines.

